



















APO
FAITH
TEMPLE

*A Going Church For
Lord*

Bishop Lambert W. Gates Sr., Sen
Bishop Nemiah Smith, Four





























































01.27.2014 12:29



01.27.2014 12:30



01.27.2014 12:34



01.27.2014 12:48



01.27.2014 12:50



01.27.2014 12:51



01.27.2014 12:58



01.27.2014 13:00



01.27.2014 14:28



01.27.2014 14:28



01.27.2014 14:34



Site: Southwest Properties Site Assessment

Property Address: 585 S. Solvay

Direction: East

Date: 1/27/13

Photographer: Lori Kozel

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 440 S. Solvay

Direction: West

Date: 1/27/13

Photographer: Michael Browning

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 564 S. Solvay

Direction: West

Date: 1/27/13

Photographer: Michael Browning

Description: Vacant and empty residential property with no structures. Note: Three piles of material are covered by snow and are obscured by the three-foot tall vegetation.



Site: Southwest Properties Site Assessment

Property Address: 9276 Melville

Direction: North

Date: 1/27/13

Photographer: Lori Kozel

Description: Vacant residential property with a collapsed building and associated debris.



Site: Southwest Properties Site Assessment

Property Address: 805 S. Green

Direction: East

Description: Vacant and empty residential property with no structures.

Date: 1/27/13

Photographer: Michael Browning



Site: Southwest Properties Site Assessment

Property Address: 702 S. Green

Direction: West

Description: Vacant and empty residential property with no structures.

Date: 1/27/13

Photographer: Lori Kozel



Site: Southwest Properties Site Assessment

Property Address: 604 S. Green

Date: 1/27/13

Direction: West

Photographer: Lori Kozel

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 589 S. Green

Date: 1/27/13

Direction: East

Photographer: Michael Browning

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 581 S. Green

Direction: East

Date: 1/27/13

Photographer: Michael Browning

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 514 S. Green

Direction: West

Date: 1/27/13

Photographer: Lori Kozel

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 406 S. Green

Direction: West

Description: Vacant and empty residential property with no structures.

Date: 1/27/13

Photographer: Lori Kozel



Site: Southwest Properties Site Assessment

Property Address: 739 Cottrell

Direction: East

Description: Vacant and empty residential property with no structures and one tire.

Date: 1/27/13

Photographer: Michael Browning



Site: Southwest Properties Site Assessment

Property Address: 226 S. Military

Direction: West

Description: Vacant and empty residential property with no structures.

Date: 1/27/13

Photographer: Lori Kozel



Site: Southwest Properties Site Assessment

Property Address: 218 S. Military

Direction: West

Description: Vacant and empty residential property with no structures.

Date: 1/27/13

Photographer: Lori Kozel



Site: Southwest Properties Site Assessment

Property Address: 212 S. Military

Direction: West

Description: Vacant and empty residential property with no structures. Note: One pile of material is covered by snow.

Date: 1/27/13

Photographer: Lori Kozel



Site: Southwest Properties Site Assessment

Property Address: 304 S. Military

Direction: West

Description: Industrial property obscured by the presence of trailers.

Date: 1/27/13

Photographer: Michael Browning



Site: Southwest Properties Site Assessment

Property Address: 341 Military

Direction: East

Date: 1/27/13

Photographer: Lori Kozel

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 335 Military

Direction: East

Date: 1/27/13

Photographer: Lori Kozel

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 745 Military

Direction: West

Description: Vacant and empty residential property with no structures.

Date: 1/27/13

Photographer: Lori Kozel



Site: Southwest Properties Site Assessment

Property Address: 1184 Morrell

Direction: East

Description: Vacant residential property with no structures but three pieces of furniture.

Date: 1/27/13

Photographer: Lori Kozel



Site: Southwest Properties Site Assessment

Property Address: 466 S. Campbell

Direction: East

Date: 1/27/13

Photographer: Michael Browning

Description: Vacant industrial property with no structures but one tire and debris.



Site: Southwest Properties Site Assessment

Property Address: 522 S. Campbell

Direction: West

Date: 1/27/13

Photographer: Michael Browning

Description: Vacant industrial property with no structures but one tire and fallen trees.



Site: Southwest Properties Site Assessment

Property Address: 6402 South Street

Direction: North

Date: 1/27/13

Photographer: Michael Browning

Description: Vacant and empty industrial property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 6410 South Street

Direction: North

Date: 1/27/13

Photographer: Michael Browning

Description: Vacant and empty industrial property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 6414 South Street

Direction: North

Date: 1/27/13

Photographer: Michael Browning

Description: Vacant and empty industrial property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 6420 South Street

Direction: North

Date: 1/27/13

Photographer: Michael Browning

Description: Vacant and empty industrial property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 511 S. Schroder

Direction: North

Date: 1/27/13

Photographer: Lori Kozel

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 521 S. Post

Direction: East

Date: 1/27/13

Photographer: Michael Browning

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 516 S. Harrington

Direction: West

Description: Vacant and empty residential property with no structures. Note: Multiple piles of material covered by snow.

Date: 1/27/13

Photographer: Michael Browning



Site: Southwest Properties Site Assessment

Property Address: 546 S. Harrington

Direction: West

Description: Vacant and empty residential property with no structures.

Date: 1/27/13

Photographer: Michael Browning



Site: Southwest Properties Site Assessment

Property Address: 605 S. Harrington

Direction: East

Description: Vacant and empty residential property with no structures.

Date: 1/27/13

Photographer: Michael Browning



Site: Southwest Properties Site Assessment

Property Address: 725 Rademacher

Direction: East

Description: Vacant and empty industrial property with no structures.

Date: 1/27/13

Photographer: Michael Browning



Site: Southwest Properties Site Assessment

Property Address: 730 Rademacher

Date: 1/27/13

Direction: East

Photographer: Michael Browning

Description: Vacant and empty industrial property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 7841 Melville

Date: 1/27/13

Direction: South

Photographer: Michael Browning

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 7837 Melville

Date: 1/27/13

Direction: South

Photographer: Michael Browning

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 7847 Medina

Date: 1/27/13

Direction: South

Photographer: Lori Kozel

Description: Vacant and empty residential property with no structures, small household trashcan located near the back of the property.



Site: Southwest Properties Site Assessment

Property Address: 227 S. Morrell

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Vacant and empty residential property with no structures, appears to be used for parking for 233 S. Morrell.



Site: Southwest Properties Site Assessment

Property Address: 230 S. Morrell

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 317 S. Morrell

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 5866 Reader

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 5873 Reader

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Empty industrial property that has been fenced in by adjacent property.



Site: Southwest Properties Site Assessment

Property Address: 8023 Thaddeus

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 8040 Thaddeus

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 8124 Thaddeus

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Vacant residential property used as parking area.



Site: Southwest Properties Site Assessment

Property Address: 8361 Thaddeus

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Residential property that has been fenced and used as part of adjacent property.



Site: Southwest Properties Site Assessment

Property Address: 9110 Thaddeus

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 9116 Thaddeus

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Vacant and empty residential property with no structures.



Site: Southwest Properties Site Assessment

Property Address: 4625 Fort Street

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Address does not exist, location of where property should be.



Site: Southwest Properties Site Assessment

Property Address: 6155 Fort Street

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Vacant industrial lot fenced into adjacent property.



Site: Southwest Properties Site Assessment

Property Address: 6249 Fort Street

Date: 1/27/13

Direction:

Photographer: Matt Beer

Description: Vacant industrial lot fenced with no structures.